

5-3-05  
12-3-2009

JULY 2004

# Work Task: 23598 - 1



## Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals

Description: Monthly AST (Above-ground Storage Tank) Visual Inspection

Visually inspect the outside of the container for (From SPCC Requirement [40 CFR 112.8(c)(6)]):

- 1. Signs of deterioration
- 2. Signs of Discharges
- 3. Signs of Accumulation of oil inside diked areas

Record finding in Work Order Close Out Comments.

Inspect all vessels on the attached list.

Work Type: 4. Environmental

Work order: 23598 Monthly AST (Above-ground Storage Tank) Visual Inspection

AGC2E000704



### Entity to Work On

Number: 710  
Name: Common Plant Services

### Personnel

Planner: MacVeigh Craig  
Supervisor: Parker Sid

### Shutdown Information

Shut entity down while work is in progress? No

### Seattle Plant

Printed by: Austell Carey  
Printed on: 5/3/2005

**Other Entities to Shut Down**

Number

Name

**Time Frame for Completing the Work**

Priority: 3 Routine

Start no earlier than: 2004/07/02 09:30:43.00

Finish no later than: 2004/07/23 09:30:43.00

Shutdown period:

Estimated duration:

Planned duration: 4.00 hours

**Job Premiums**

Job type:

Shift:

**Backlog Information:**

Probability of Satisfaction: High

Material availability: Material not required

Estimated material availability date:

**Seattle Plant**

Printed by: Austell Carey

Printed on: 5/3/2005

**Failure Information**

Generate failure analysis information: No  
Reason for failure: Closed  
Root cause:  
Action taken: Closed  
Equipment failed due to:  
Entity:  
Catalog item:

**Requirements**

Part/Service	Quantity	Item Number	Probability of Satisfaction	Availability	Estimated Material Availability Date	Storeroom
--------------	----------	-------------	-----------------------------	--------------	--------------------------------------	-----------

Trade	Quantity	Time Required
-------	----------	---------------

PM Lube Spec	1.00	4.00 hours
--------------	------	------------

**Safety Instructions for this Work****Activities****Seattle Plant**

Printed by: Austell Carey  
Printed on: 5/3/2005

Work Task: Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals

Activity Number	Activity	Record Statistics	Record Downtime	Component Movement	Calibration Instrument Used	Comments
<input type="checkbox"/>						
Processed:		Processed on:		Done by:		

AGC2E000707

Seattle Plant

Printed by: Austell Carey  
 Printed on: 5/3/2005